



# Houston Forensic Science Center

Comparative and Analytical Division - Toxicology

## Hamilton® Maintenance Log

Manufacturer: Hamilton Company

Model: Microlab® 600

Serial Number: 1742 or 7903

Type of Maintenance*	Recommended maintenance schedule*	Check if performed
Replacing Valves	Change every 1.5 to 2 years.	✓
Replacing Cross Tube	Change when valves are changed.	✓
Replacing the Syringes	Change if solution is leaking past the plunger.	Reinstalled gv 05/28/2024
Replace Tubing	When becomes bent/kinked or discolored or with annual service.	✓
Cleaning and Lube Service	Annually by Hamilton Company Service Center.	gv 05/28/2024
Replacing Batteries	Battery should have a lifespan of 10 years. When battery fails send controller to Hamilton Company Service Center.	
Updating Firmware or Software Version	As updated by Hamilton Company	
	Version	
	Firmware FRGA	gv 05/28/2024
	Firmware Runtime	
	Software	
Operating System		
<b>Comments:</b> Received back from Hamilton company on 05/28/2024 - gv 05/28/2024 gv 05/28/2024		

\*Adapted from Hamilton® user manual.

Signature: gv

Date: 05/28/2024