



Houston Forensic Science Center

Comparative and Analytical Division - Toxicology

Hamilton® Maintenance Log

Manufacturer: Hamilton Company

Model: Microlab® 600

Serial Number: 1742 or 7903

Type of Maintenance*	Recommended maintenance schedule*	Check if performed	
Replacing Valves	Change every 1.5 to 2 years.	/	
Replacing Cross Tube	Change when valves are changed.		
Replacing the Syringes	Change if solution is leaking past the plunger.		
Replace Tubing	When becomes bent/kinked or discolored or with annual service.		
Cleaning and Lube Service	Annually by Hamilton Company Service Center.		✓
Replacing Batteries	Battery should have a lifespan of 10 years. When battery fails send controller to Hamilton Company Service Center.	/	
Updating Firmware or Software Version	As updated by Hamilton Company		
	Version		
	Firmware FRGA		/
	Firmware Runtime		
	Software		
Operating System			
<p>Comments: Disassembled and decontaminated on 9/14/2024. Shipping to Hamilton on 9/14/2024 - gv 9/14/24</p>			

*Adapted from Hamilton® user manual.

Signature: _____

Date: _____


 9/14/2024