



Houston Forensic Science Center

Comparative and Analytical Division - Toxicology

Hamilton® Maintenance Log

Manufacturer: Hamilton Company

Model: Microlab® 600

Serial Number: 1742 or 7903

Type of Maintenance*	Recommended maintenance schedule*	Check if performed	
Replacing Valves	Change every 1.5 to 2 years.	✓	
Replacing Cross Tube	Change when valves are changed.	✓	
Replacing the Syringes	Change if solution is leaking past the plunger.	Reinstalled -gv 10/18/2024	
Replace Tubing	When becomes bent/kinked or discolored or with annual service.	✓	
Cleaning and Lube Service	Annually by Hamilton Company Service Center.	gv 10/18/2024	
Replacing Batteries	Battery should have a lifespan of 10 years. When battery fails send controller to Hamilton Company Service Center.		
Updating Firmware or Software Version	As updated by Hamilton Company		
	Version		
	Firmware FRGA	gv 10/18/2024	
	Firmware Runtime		
Software			
Operating System			
Comments: Received back from Hamilton on 10/18/2024 -gv 10/18/2024			

*Adapted from Hamilton® user manual.

Signature: _____

Date: 10/18/2024