



Belair Systems Inc.
 Service, Installation, and Repairs Division
 28364 S. Western Ave. #302
 Rancho Palos Verdes, Ca. 90275

Office: (310) 528-4293
 Fax: (310) 831-1684

Date: 6/11/2024

Service Report

Address & Description: 500 JEFFERSON STREET 0 Houston, TX 77002	Company:	HOUSTON FORENSIC SCIENCE	
	Contact:	Dayong Lee	
	Telephone #:	dlee@hfscctx.gov	
	Fax/Email:	#REF!	
	Cuts. PO#	Machine Type	Serial No.
		Generator: H2PEMPD-510-100	S/N 19PLD5150
Job No.	Job Completion Date	Location	
8002	6/10/2024		
Warranty	Event	Technician	
	121596	O. Delgado	
Reason For Visit:	Recommendation to Customer:		
Generator: H2PEMPD-510-100 S/N 19PLD5150 Service	***Parker to send RA to customer replace the generator/replace cell. Call Belair Systems Inc. for all of your preventative maintenance, installation, and certification needs!		

Model #:	Generator: H2PEMPD-510-100
Serial #'s:	S/N 19PLD5150

Description of Service/Installation:

The tech found the generator turned off. The tech turned on the generator and the generator had a service alarm on, another low pressure alarm and the generator blocked. The tech closed the outlet valve and then the tech performed a hard reset to be able to turn on the generator, once the generator reset was done, the generator started working normally for a few minutes and suddenly the cell exploded. This means that the problem came from the cell which was not working correctly. The tech turned off the generator to be dismantled and packaged to be sent to Parker to replace the cell. The customer must contact Parker to follow the corresponding instructions to have the generator sent back.

Parts	Quantity	Description
FIELD SERVICE - AGS		

Time Table							Hourly Total	Notes:
Mon	Tues	Wed	Thur	Fri	Sat	Sun		

Date:	6/10/2024	Customer Signature:	
-------	-----------	---------------------	--