



Houston Forensic Science Center

Comparative and Analytical Division - Toxicology

Tecan Maintenance Log

Freedom EVO 75/Hydroflex Plate Washer

Instrument: Tecan (SN 908005778) or Tecan-2 (SN 1010008386)

Date	Rinse and Fill Wash Bottles	Prime Tecan	Prime Plate Washer	Empty Waste Containers	Monthly Maintenance		Comments	Signature
					Acid/Base	Hydroflex		
6/19/18	✓	✓	✓	✓	X	X		RM
6/20/18	✓	✓	✓	✓	X	X	Collision error. Restarted and reinitialized Tecan-2, ran 10x test run of wipers. Test runs successful. <i>ell</i> 6/20/18	RM
6/22/18	✓	✓	✓	✓	X	X	Ron Veselenak from Tecan here to look at the RomA arm. See service report.	RM
								<i>ell</i> 6/27/18

Form Complete Date/Signature:

[Signature] 6/27/18