



Belair Systems Inc.  
 Service, Installation, and Repairs Division  
 28364 S. Western Ave. #302  
 Rancho Palos Verdes, Ca. 90275

Office: (310) 528-4293  
 Fax: (310) 831-1684

Date: 9/5/2023

**Service Report**

Address & Description:  500 JEFFERSON STREET  13TH FLOOR  Houston, TX 77002	Company:	HOUSTON FORENSIC SCIENCE		
	Contact:	Dayong Lee		
	Telephone #:	dlee@hfsctx.gov		
	Fax/Email:	#REF!		
	<b>Cuts. PO#</b>	<b>Machine Type</b>	<b>Serial No.</b>	
	H2PEMPD-510-100	19PLD5150		
<b>Job No.</b>	<b>Job Completion Date</b>	<b>Location</b>		
7385	9/5/2023			
<b>Warranty</b>	<b>Event</b>	<b>Technician</b>		
	120262	J. Randall		
<b>Reason For Visit:</b>	<b>Recommendation to Customer:</b>			
H2PEMPD-510-100 19PLD5150 Service	Call Belair Systems Inc. for all of your preventative maintenance, installation, and certification needs!			

<b>Model #:</b>	H2PEMPD-510-100
<b>Serial #'s:</b>	19PLD5150

**Description of Service/Installation:**

Tech arrived to find loaner still installed. Tech located customers original one for replacement. Tech drained and prepared loaner for shipment. Tech installed replacement and completed pm per customer request. Hours run 28579. Service in 6277. After pm tech attempted to reset service timer but did not have any luck. Set all pressures to match. Tech located a lot of spare parts organized for customers future use. System performing to spec.

Parts	Quantity	Description
Installation service		

Time Table							Hourly Total	Notes:
Mon	Tues	Wed	Thur	Fri	Sat	Sun		

Date:	9/5/2023	Customer Signature:	
-------	----------	---------------------	--